

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

1. Name of the Officer : NEETHU. A
2. Name of the School : Ahalia Public School
3. Location with name of Education District/Sub. District : Kozhippara - PALAKKAD
4. Classification of Building as specified in Column 4 of the application for fitness certificate and size

## Ground Floor

Class room	: 5 x 6.00 x 7.43 x 3.60m
Store room	: 6.00 x 3.60 x 3.60 m
Boys toilet	: 6.00 x 3.60 x 3.60 m
Staff room	: 6.00 x 3.60 x 3.60 m
Girls toilet	: 2 x 6.00 x 3.60 x 3.60 m
Stair toilet	: 7.57 x 3.10 x 3.60m
	: 5.17 x 3.20 x 3.60m

## Sloped Roof

Audio visual room	: 1 x 4.00 x 6.00m
Class room	: 8 x 6.00 x 4.00m
Store room	: 9 x 2.38 x 3.38m
Waiting Area	: 1 x 6.00 x 6.00m
Toilet Block	: 1 x 6.00 x 4.00m
Activity room	: 6.00 x 3.385m
Staff room	: 4.00 x 6.00m
Office room	: 6.00 x 2.77m
Head miss room	: 1 x 4.42 x 3.30m
Toilet	: 2 x 2.38 x 1.57m
	1 x 1.35 x 1.87m

## First Floor

Class room	: 7 x 6.00 x 7.43 x 3.60m
Stair room	: 1 x 7.57 x 3.20m
	1 x 5.17 x 3.20m

## Lab Block

### Ground Floor

Lab room	: 4 x 8.00 x 3.89 x 3.60m
Sick room	: 1 x 8.00 x 3.89 x 3.60m
Girls Toilet	: 2 x 3.89 x 1.93 x 3.60m

Hall : 1 x 8.00 x 20.35 x 3.60m  
Store and server room : 8.00 x 3.00 x 3.60m

**First Floor**

Lab room : 1 x 8.00 x 12.12 x 3.60m  
Lab room : 1 x 8.00 x 7.12 x 3.60m  
Library : 1 x 8.00 x 23.58m x 3.60m

**Second Floor**

Computer Lab : 1 x 6.87 x 7.12 x 3.60m  
Language lab : 2 x 8.00 x 12.12 x 3.60m  
Audio Visual room : 1 x 23.10 x 11.23 x 3.60m

5. Period for which the certificate is issued : 2023 – 24 Academic Year
6. Nature of defects, if any
- (a) Foundation and basement : NIL
- (b) Super structure : NIL
- (c) Doors and Windows : NIL
- (d) Wood work wrought and put up : NIL
- (e) Roof : NIL
- (f) Flooring : NIL
- (g) Miscellaneous (Cracks, etc.) : NIL
7. Any major defects noticed which will render the building unsafe in any manner : NIL
8. Whether maintenance works have been done property : Yes
9. Whether the structure is sound or not for conducting classes : Yes, the structure is sound for conducting classes under normal weather condition.

*Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observation if deemed necessary for the certificate may be furnished separately this certificate.*


**CERTIFICATE**

Certified that the school building was inspected by me on 19.12.2023 and found to be fit to conduct classes, for the period 2023-24 Academic year for the reasons stated above.

Place : Elappully

Date : 19.12.2023



  
**NEETHU.A**  
PEN: 941525  
Assistant Engineer  
LID & EW (LSGD)  
Elappully Section