FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

1.	Name of the Officer	: NEETHU.A
2.	Name of the School	: Ahalia Public School
З.	Location with name of Education District/Sub. District	:Kozhippara -Palakkad
4,	Classification of Building as specified in Column 4 of	
	the application for fitness certificate and size	
	Ground Floor	۲.
	Class Room	5x6.00x7.43x3.60 m
	Store Roo;n	: 6.00x3.60x3.60 m
	Eoys Toilet	: 6.00x3.60x3.60 m
	Statt Room	: 6.00x3.60x3.60 m
	Girls Toilet	2x6.00x3.60x3.60 m
	Stair Toilct	: 7.57x3.10v3.60 m
		: 5.17x3.20x3.60 m
	Sloped Roof	
	Audio Visual Room	: 1x4.00x6.00m
	Class room	: 8x6.00x4.00m
	Store Room	: 9x2.38x3.38m
19	Walling Area	: 1x6.00x6.00m
	Toilet Block	. 1x6.00x4.00m
	Activity Room	: 6.00x3.385m
	Staff Room	: 4.00x6.00m
	Office Room	: 6.00x2.77m
	Head Miss Room	: 1x4.42x3.30m
	Toilet	: 2x2.38x1.57m
	<i>'</i>	. 1x1.35x1.87m
	First Floor	
	Class Doom	· 7×6 00×7 43×3 80m

Class Room

: 7x6.00x7.43x3.60m

	Stair Room	: 1x7.57x3.20m	
		: 1x5.17x3.20m	
	Lab Block		
	Ground Floor		
	Lab Room	: 4x8.00x3.89x3.60m	
		: 1x8.00x3.98x3.60m	
	Sick Room		
	Girls Toilet	: 2x3.89x1.93x3.60m	
	Hall	: 1x8.00x20.35x3.60m	
	Store And Server Room	: 8.00x3.00x3.60m	
	First Floor		
	Lab Room	: 1x8.00x12.12x3.60m	
	Lab Room	: 1x8.00x7.12x3.60m	
	Library	: 1x8.00x23.58mx3.60m	
	Second Floor		
	Computer Lab	: 1x6.87x7.12x3.60m : 2x8.00x12.12x3.60m : 1x23.10x11.23x3.60m	
	Language Lab		
	Audio Visual Room		
5.	Period for which the certificate is issued	: 2024 - 2025 Academic Year	
6.	Nature of defects, if any		
	(a) Foundation and basement	: NIL	
	(b) Super structure	: NIL	
	(c) Doors and Windows	: NIL	
	(d) Wood work wrought and put up	: NIL	
	(e) Roof	: NIL	
	(f) Flooring	: NIL	
	(g) Miscellaneous (Cracks, etc.)	: NIL	
7.	Any major defects noticed which will render the building unsafe in any manner	: NIL	
8.	Whether maintenance works have been done property	: Yes	
9.	Whether the structure is sound or not for conducting classes	: Yes , the structure is sound for conducting classes under normal weather condition.	

2

•

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observation if deemed necessary for the certificate may be furnished separately this certificate.

CERTIFICATE

Certified that the school building was inspected by me on ...11/02/2025..... and found to be fit to conduct classes, for the period 2024 - 2025..... Academic year for the reasons stated above.

Place : Elappully Date : 11/02/2025



Assistant Egiginaer Local Self Government Department Elappully Section

AHALIA PUBLIC SCHOOL PALAKKAD-678 557

